


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission – Speaker Box



Front View




Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission



Front View



Side View 1

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission



Side View 2