


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: TL74208

Radiated Emission – Base Unit



Front View




Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: TL78208

Radiated Emission – Base Unit



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: TL74208

Conducted Emission



Front View




Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: TL74208

Conducted Emission



Left Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: TL78208

Conducted Emission



Front View




Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: TL78208

Conducted Emission



Left Side View