



# INTERTEK TESTING SERVICES

## The Worst Case Configuration Photographs

Radiated Emission - Dect



Front View




Rear View

# INTERTEK TESTING SERVICES

## The Worst Case Configuration Photographs

AC Conducted Emission



Front View



Side View 1

# INTERTEK TESTING SERVICES

## The Worst Case Configuration Photographs

### AC Conducted Emission



Side View 2