



Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	35

EUT WITH TOP COVER REMOVED




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	36

DEMODULATOR BOARD, REMOVED




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	37

COMPONENT SIDE OF DEMODULATOR BOARD




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	38

DEMODULATOR BOARD WITH SHIELD COVERS REMOVED





Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	39

SOLDER SIDE OF MAIN CIRCUIT BOARD




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	40

POWER SUPPLY BOARD, REMOVED



Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	41

COMPONENT SIDE OF POWER SUPPLY BOARD




Electromagnetic Engineering Services, Inc.

11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121
(619) 793-9911 Voice; (619) 259-7170 Fax


Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	42

SOLDER SIDE OF POWER SUPPLY BOARD




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	43

INTERFACE BOARD AND CORE BOARD, REMOVED




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	44

COMPONENT SIDE OF INTERFACE BOARD AND CORE BOARD




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	45

SOLDER SIDE OF INTERFACE BOARD AND CORE BOARD




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	46

CLOSE-UP VIEW OF INTERFACE BOARD CONNECTORS




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	47

TRANSFER SWITCH MODULE WITH SHIELD COVERS REMOVED, RIGHT SIDE




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	48

TRANSFER SWITCH MODULE WITH SHIELD COVERS REMOVED, LEFT SIDE




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #	Report #	Page #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095	49

FRONT PANEL




REAR VIEW OF FRONT PANEL




Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121	
(619) 793-9911 Voice; (619) 259-7170 Fax			
Revision	Date	Document Name	FCC ID #
A	4/27/98	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R
Page #	Report #		
50	98-095		

Electron		11696 Sorrento Valley Road, Suite F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax	
Revision	Document Name	FCC ID #	Report #
A	General Instrument Corporation DSR-421 FCC Certification Report	F2NDSR421R	98-095
4/2			Page #
			51

COMPONENT SIDE OF DISPLAY BOARD



SOLDER SIDE OF DISPLAY BOARD



Electromagnetic Engineering Services, Inc. 11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 793-9911 Voice; (619) 259-7170 Fax		Revision	A
Page #	Report #	Date	4/27/98
52	98-095	Document Name	General Instrument Corporation DSR-421 FCC Certification Report
	F2NDSR421R	FCC ID #	F2NDSR421R