



INTERNAL PHOTOGRAPHS

This document contains 10 photographs


Photograph No.1
LC-104-PIMW/LC-124-PIMW detector internal view




Photograph No.2
Main PCB front view




Photograph No.3
Main PCB with RF module removed




Photograph No.4
Main PCB without RF module



Photograph No.5
Second side of the main PCB




Photograph No.6
RF module front view




Photograph No.7
RF module PCB front view



Photograph No.8
Second side of the RF module



Photograph No.9
Second side of the RF module



Photograph No.10
Shielding compartments of the RF PCB

