

Prüfbericht-Nr.: <i>Test report no.:</i>	60374262-Appendix	Auftrags-Nr.: <i>Order no.:</i>	23870363 030	Seite 1 von 7 <i>Page 1 of 7</i>
Kunden-Referenz-Nr.: <i>Client reference no.:</i>	1288983	Auftragsdatum: <i>Order date:</i>	2020.04.14	
Auftraggeber: <i>Client:</i>	IKEA of Sweden AB			
Prüfgegenstand: <i>Test item:</i>	STYRBAR Remote control			
Bezeichnung / Typ-Nr.: <i>Identification / Type no.:</i>	E2002 FCC ID: FHO-E2002			
Auftrags-Inhalt: <i>Order content:</i>	FCC Compliance testing			
Prüfgrundlage: <i>Test specification:</i>	FCC 47 CFR Part 15B with parts 15.107 & 15.109 ANSI C63.4: 2014			
Wareneingangsdatum: <i>Date of sample receipt:</i>	2020.04.23			
Prüfmuster-Nr.: <i>Test sample no.:</i>	See section 2.3			
Prüfzeitraum: <i>Testing period:</i>	2020.04.29 - 2020.05.06			
Ort der Prüfung: <i>Place of testing:</i>	Lund, Sweden			
Prüflaboratorium: <i>Testing laboratory:</i>	TÜV Rheinland Sweden			
Prüfergebnis*: <i>Test result*:</i>	Pass			
überprüft von: <i>reviewed by:</i>	<input checked="" type="checkbox"/> 	genehmigt von: <i>authorized by:</i>	<input checked="" type="checkbox"/> 	
Datum: 2020.06.29 <i>Date:</i>	Signed by: Fariborz Abasi	Datum: 2020.06.29 <i>Date:</i>	Signed by: Per Isacson	
Stellung / Position:	Test Engineer	Stellung / Position:	Lab Manager	
Sonstiges / Other:				
Zustand des Prüfgegenstandes bei Anlieferung: <i>Condition of the test item at delivery:</i>		Prüfmuster vollständig und unbeschädigt <i>Test item complete and undamaged</i>		
* Legende:	1 = sehr gut 2 = gut 3 = befriedigend 4 = ausreichend 5 = mangelhaft P(ass) = entspricht o.g. Prüfgrundlage(n) F(ail) = entspricht nicht o.g. Prüfgrundlage(n) N/A = nicht anwendbar N/T = nicht getestet			
* Legend:	1 = very good 2 = good 3 = satisfactory 4 = sufficient 5 = poor P(ass) = passed a.m. test specification(s) F(ail) = failed a.m. test specification(s) N/A = not applicable N/T = not tested			
<p>Dieser Prüfbericht bezieht sich nur auf das o.g. Prüfmuster und darf ohne Genehmigung der Prüfstelle nicht auszugsweise vervielfältigt werden. Dieser Bericht berechtigt nicht zur Verwendung eines Prüfzeichens. <i>This test report only relates to the a. m. test sample. Without permission of the test center this test report is not permitted to be duplicated in extracts.</i></p>				

Revision History

REVISION	DATE	REMARKS	AUTHOR
001	2020.06.29		Sam Ebadeh

Note: Latest revision report will replace all previous reports

This report based on FCC Part 15B no JBP Template version 1.1

Summary of Test Results

FCC 47 CFR Rule Part	Test Description	Applicability	Report Section	RESULT	REMARKS
15.107	AC Power Line Conducted Emissions (Unintentional Radiators)	YES	4.1	N/A	Battery powered only
15.109	Radiated Emissions (Unintentional Radiators)	YES	4.2	PASS	

Possible test case verdicts:

- Test case does not apply to the test object: N/A
- Test object complies with the requirement: PASS or COMPLIANT
- Test object does not meet the requirement: FAIL or NOT COMPLIANT
- Test case not performed on the test object: N.P.

Table of Contents

1. GENERAL INFORMATION.....	4
1.1 Test Site.....	4
1.2 Client Information.....	4
2. PHOTOGRAPHS.....	5

1. GENERAL INFORMATION

1.1 Test Site

Test Facility:	TÜV Rheinland Sweden AB
Address:	Mobilvägen 10
	223 62 Lund
	Sweden
Swedac Registration Number:	10325
FCC Test Firm Registration Number:	517458
ISED Test Site Registration Number:	24753

1.2 Client Information

Company Name:	IKEA of Sweden AB
Address:	Tulpanvägen 8
	34381 Älmhult
	Sweden
Contact Person:	Torbjörn Samuelsson
Contact e-Mail / Telephone	torbjorn.samuelsson@inter.ikea.com

2. PHOTOGRAPHS

Photo 1: Chamber set up for 30 MHz – 1 GHz



Photo 2: Chamber set up for 30 MHz – 1 GHz




Photo 3: Chamber set up for 1 GHz – 18 GHz




Photo 4: Chamber set up for 1 GHz – 18 GHz




Photo 5: Close up of EUT in chamber

