







6. Inside View of Rear "Cover" Assembly.




7. Bottom View of RT-138F With Bottom Cover Removed.




8. Left Side View of RT-138F, Showing Transmitter/Receiver Sub-Assembly, With Shield Cover Removed.




9. Close-up View of Front Portion of
Transmitter/Receiver Sub-Assembly.




10. Close-up View of Rear Portion of T/R Sub-Assembly.




11. Modulator/VCO Sub-Assembly (Removed From Right Side of Chassis) With Shield Cover Removed.




12. Close-up View of Front Portion of VCO/Modulator Sub-Assembly (Small Shield Cover Removed).




13. Close-up View of Rear Portion of VCO/Modulator Sub-Assembly.




14. View of Guard Receiver Sub-Assembly.




15. Rear, Side View of Power Supply Sub-Assembly.



16. Side View of Power Supply Sub-Assembly, With Shield Cover Removed.



17. Rear Portion of Audio P.C. Board Sub-Assembly.



18. Front Portion of Audio P.C. Board Sub-Assembly.



19. Front View of C-1000 Control Unit (Used With RT-130F Transceiver).