



Spectrum Research & Testing Lab., Inc.  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City, Taoyuan County 320, Taiwan  
(R.O.C.)

## Photos of Testing

- Radiated test (9 k - 30 MHz ,TX and standby)





Spectrum Research & Testing Lab., Inc.  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City, Taoyuan County 320, Taiwan  
(R.O.C.)

- Radiated test (9 k - 30 MHz ,link)





Spectrum Research & Testing Lab., Inc.  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City, Taoyuan County 320, Taiwan  
(R.O.C.)

- Radiated test (below 1G ,TX and standby)





Spectrum Research & Testing Lab., Inc.  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City, Taoyuan County 320, Taiwan  
(R.O.C.)

- Radiated test (below 1G ,Link)





Spectrum Research & Testing Lab., Inc.  
No.167, Ln. 780, Shan-Tong Rd., Ling 8, Shan-Tong Li, Chung-Li City, Taoyuan County 320, Taiwan  
(R.O.C.)

- Radiated test (above 1G , TX and standby)





Spectrum Research & Testing Lab., Inc.  
No.167,Ln. 780, Shan-Tong Rd.,Ling 8, Shan-Tong Li, Chung-Li City, Taoyuan County 320, Taiwan  
(R.O.C.)

- Radiated test (above 1G , Link)

