



**Spectrum Research & Testing Lab., Inc.**  
No.167,Ln. 780, Shan-Tong Rd.,Ling 8, Shan-Tong Li,  
Chung-Li City, Taoyuan County 320, Taiwan (R.O.C.)

## PHOTOS OF TESTING

- Radiated test (below 1G , TX)





**Spectrum Research & Testing Lab., Inc.**  
No.167,Ln. 780, Shan-Tong Rd.,Ling 8, Shan-Tong Li,  
Chung-Li City, Taoyuan County 320, Taiwan (R.O.C.)

- Radiated test (above 1G , TX)

