



ID: GM8MS9000E

REPORT NO: ER/2003/A0004

DATE: OCT. 15,2003

APPENDIX 3

INTERNAL PHOTOGRAPHS OF EUT

The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan.


TEL: 886-2-22993939

FAX: 886-2-22982698

Internal of EUT – Open



Internal of EUT – 1



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.


SGS Taiwan Ltd.

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan.


TEL: 886-2-22993939

FAX: 886-2-22982698


Internal of EUT – 2



Internal of EUT – 3



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

Internal of EUT – 4

The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.
TEL: 886-2-22993939

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan.
FAX: 886-2-22982698