







COVER REMOVED, PWR SWY & ANTENNA SWITCH VISIBLE



COVER REMOVED, CABLES DIS-CONNECTED




CLOSE UP, POWER SUPPLY





CLOSE UP, ANTENNA SWITCH ASSEMBLY

DIGITAL PCA & 8.4 GHz COVER REMOVED, 8.4 GHz RF PCA




CLOSE UP, DIGITAL PCA






CLOSE-UP, 2.4 GHZ PCA



DIS-ASSEMBLED TEST RADIO



FILTER ADDED TO INSIDE OF RADIO @ MS CONNECTOR
TO REDUCE EMISSIONS. THIS WILL BE REMOVED
ASAP & A PERMISSIVE CHANGE FILED (7-2-97 *SL*)