


Report No.: EED32O80799103 Page 48 of 57

## 7 PHOTOGRAPHS OF TEST SETUP

Test model No.: M01584-D



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O80799103



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



**Conducted Emissions Test Setup** 











Page 49 of 57