


Prüfbericht - Nr.:
Test Report No.:

16010007 001

Seite 28 von 31
Page 28 of 31

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Radiation Measurement Below 1GHz



Prüfbericht - Nr.:
Test Report No.:

16010007 001

Seite 29 von 31
Page 29 of 31

Photograph 2: Set-up for Radiation Measurement above 1GHz



Prüfbericht - Nr.:
Test Report No.:

16010007 001

Seite 30 von 31
Page 30 of 31

Photograph 3: Set-up for Conducted Emission of AC mains

