



7. Photographs of the Test Set-Up

Photograph 1: Set-up for Radiation Measurement below 1GHz



Prüfbericht - Nr.: 16061108 001
Test Report No.:

Seite 29 von 30
Page 29 of 30

Photograph 2: Set-up for Radiation Measurement above 1GHz

