


Prüfbericht - Nr.:
Test Report No.:

16012110 001

Seite 24 von 26
Page 24 of 26

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Radiation Measurement Below 1GHz



Prüfbericht - Nr.:
Test Report No.:

16012110 001

Seite 25 von 26
Page 25 of 26

Photograph 2: Set-up for Radiation Measurement above 1GHz

