

5.4 Setup Photographs

Photo:





Report Number: 100619930DEN-001 Issued: 2/17/2012

Photo:



Axis 2 (EUT Vertical)



Axis 3 (EUT Vertical & Rotated 90 degrees)



Photo:

Antenna Setups – CC1 30 – 1000MHz

