























## A3.7 LTE Band 7










## A3.8 LTE Band 25











## A3.9 LTE Band 30







## A3.10 LTE Band 41










## A3.11 LTE Band 66













## A3.12 NR n2











## A3.13 NR n66













## A4. Transmitter unwanted emissions (spurious) Test Result

### A4.1 LTE 2UL 5B

