

ADDITIONAL EXTERNAL CONSTRUCTION PHOTOS



SIDE VIEW OF TRANSMITTER

The transmitter is sandwiched between two other racks. The right side of this transmitter can be seen that it is simply a flat metal skin that runs the entire length down to the floor.

ADDITIONAL EXTERNAL CONSTRUCTION PHOTOS



The transmitter is sandwiched between two other racks. This picture of the right side of this transmitter is taken from a different angle than the previous picture. The flat metal skin that runs the entire length down to the floor can be seen here. In this picture the back door has been removed and the yellow material on the side of the cabinet is a temporary Post-It Note.

ADDITIONAL EXTERNAL CONSTRUCTION PHOTOS



OTHER SIDE OF TRANSMITTER

The left side of the transmitter is beside a tall rack which blocks the view of the transmitter left side. The left side of the transmitter has a metal skin of the same construction and color as the picture on the preceding page.