



**Spectrum Research
& Testing Lab., Inc.**

No. 101-10, Ling 8,
Shan-Tong Li, Chung-Li
City, Taoyuan, Taiwan,
R.O.C.

TEST REPORT

Reference No.: A07112106
Report No.: FCCA07112106
FCC ID: HQXAGP-Y6
Page:45 of 48
Date: Nov. 29, 2007

11. PHOTOS OF TESTING

- Conducted Emission test





**Spectrum Research
& Testing Lab., Inc.**

No. 101-10, Ling 8,
Shan-Tong Li, Chung-Li
City, Taoyuan, Taiwan,
R.O.C.

TEST REPORT

Reference No.: A07112106
Report No.: FCCA07112106
FCC ID: HQXAGP-Y6
Page:46 of 48
Date: Nov. 29, 2007

- Radiated Emission test (below 1 G)





**Spectrum Research
& Testing Lab., Inc.**

No. 101-10, Ling 8,
Shan-Tong Li, Chung-Li
City, Taoyuan, Taiwan,
R.O.C.

TEST REPORT

Reference No.: A07112106
Report No.: FCCA07112106
FCC ID: HQXAGP-Y6
Page:47 of 48
Date: Nov. 29, 2007

- Radiated Emission test (above 1 G)

