

Summary of change for 12BAN

1. Changed Component

The following parts are changed. Also the slightly pattern around the switch is changed.

Item	Part name	Before	After
Switch 3	Switch	Photo1	Photo2




Photo 1




Photo 2