



APPENDIX 3: Photographs of test setup

Radiated Spurious Emission (Test model number: DNNS122)


Front



Rear (below 1 GHz)



Rear (above 1 GHz)




Radiated Spurious Emission
(Test model number: DNNS124)

Front



Rear (below 1 GHz)



Rear (above 1 GHz)



Antenna Terminal Conducted Tests
(Test model number: DNNS122)



Photo 1




Photo 2

Antenna Terminal Conducted Tests
(Test model number: DNNS124)




Photo 1



Photo 2

End of Report