


APPENDIX 3: Photographs of test setup

Radiated Spurious Emission
(Test model number: DNNS122)

Front



Rear (below 1 GHz)



Rear (above 1 GHz)




Radiated Spurious Emission
(Test model number: DNNS124)

Front



Rear (below 1 GHz)



Rear (above 1 GHz)



Antenna Terminal Conducted Tests
(Test model number: DNNS122)




Photo 1




Photo 2

UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401

Antenna Terminal Conducted Tests
(Test model number: DNNS124)



Photo 1



Photo 2

End of Report

UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401