

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2


Worst Case Position

Below 1 GHz: Horizontal: X-axis/ Vertical: X-axis
Above 1 GHz: Horizontal: X-axis/ Vertical: Y-axis


X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report