



PHOTOGRAPHS OF THE TEST CONFIGURATION CONDUCTED EMISSION TEST (Antenna 1)
















CONDUCTED EMISSION TEST (Antenna 3)








CONDUCTED EMISSION TEST (Antenna 4)







CONDUCTED EMISSION TEST (Antenna 5) 920722R01 920722R01






CONDUCTED EMISSION TEST (Antenna 6)








CONDUCTED EMISSION TEST (Antenna 7) 920722R01 - 1 920722R01






CONDUCTED EMISSION TEST (Antenna 8) 920722R01 920722R01














CONDUCTED EMISSION TEST (Antenna 10) 920722R01 920722R01






CONDUCTED EMISSION TEST (Antenna 11)










RADIATED EMISSION TEST (Antenna 1)









RADIATED EMISSION TEST (Antenna 3)







RADIATED EMISSION TEST (Antenna 5)







RADIATED EMISSION TEST (Antenna 6)








RADIATED EMISSION TEST (Antenna 7)



























RADIATED EMISSION TEST (Antenna 11)

