

CONFIDENTIAL

31 January 2019

## Polar 3N Internal Pictures



---

**POLAR**®

CONFIDENTIAL

31 January 2019



Figure 1. The whole device.




Figure 2. Display module and HW part with back case separated.



CONFIDENTIAL

31 January 2019




Figure 3. PWB in back case.




Figure 4. PWB removed, battery in back case.




Figure 5. PWB from component side.



CONFIDENTIAL

31 January 2019




Figure 6. PWB from other side. Vibra motor on left hand side.




Figure 7. PWB from component side without RF shields.



CONFIDENTIAL

31 January 2019




Figure 8. PWB with separated RF shields




Figure 9. Battery removed from back case. Plate battery assembly in the middle.



CONFIDENTIAL

31 January 2019




Figure 10. Optical heart rate PWB in its place.



CONFIDENTIAL

31 January 2019




Figure 11. OHR PWB from LED side.




Figure 12. OHR PWB from component side.

