



**APPENDIX 3: Photographs of test setup**

**Radiated Spurious Emission**


**Front**



**Rear (Blow 1 GHz)**




**Rear (Above 1 GHz)**




**Pre-check of Worst Case Position**

**0 deg.**




**30 deg.**




---

**Antenna Terminal Conducted Tests**



**Photo 1**



**Photo 2**

**End of Report**