




83K000068




- 6. Photos of testing
  - I. Computer left side view
  - J. Computer right side view



6. Photos of testing

K. Computer inside whole view

L. Computer case inside view of cover



6. Photos of testing

M. Computer chassis inside view



N. Computer front panel inside view



6. Photos of testing

O. Power supply whole view



P. Computer supply inside view



6. Photos of testing

Q. power supply component side

R. power supply solder side



6. Photos of testing

S. AGP PCI VGA card whole view

R. Intel Pentium II – 400 CPU whole view

