


ANNEX C INTERNAL PHOTOS




153783_10.JPG: PK1, top view (side covers and dummy emergency key removed)

ANNEX C INTERNAL PHOTOS




153783_11.JPG: PK1, top view (side covers, battery cover and battery removed)

ANNEX C INTERNAL PHOTOS




153783_12.JPG: PK1, bottom view (side covers and rear cover removed)

ANNEX C INTERNAL PHOTOS



153783_13.JPG: PK1, PCB, bottom view

ANNEX C INTERNAL PHOTOS



153783_14.JPG: PK1, PCB, top view