



## **INTERNAL PHOTOGRAPHS**

This document contains 6 photographs


Photograph No.1  
Wireless VITRON glass-break detector internal view




**Photograph No.2**  
**VITRON detector internal view with battery removed**




Photograph No.3  
VITRON detector PCB front view



Photograph No.4  
VITRON detector PCB second side view



Photograph No.5  
PCB with shield removed



Photograph No.6  
Antenna assembly

