

### Annex A: Photographs of the Test Set-up

**Photo 1: Radiated Emission** 




**Photo 2: Radiated Emission** 



2021-03-02 Page 1 of 5



**Photo 3: Conducted Emission** 



2021-03-02 Page 2 of 5



# Annex B: External Photographs of the EUT

### Photo 1:



#### Photo 2:



2021-03-02 Page 3 of 5

Test report no.: 1-1068/20-01-07




# Annex C: Internal Photographs of the EUT

### Photo 1:



### Photo 2:




2021-03-02 Page 4 of 5



### Photo 3:



### Photo 4:



2021-03-02 Page 5 of 5