

Annex A: Photographs of the Test Set-up

Photo 1: Radiated Emission




Photo 2: Radiated Emission



2021-03-02 Page 1 of 5



Photo 3: Conducted Emission



2021-03-02 Page 2 of 5



Annex B: External Photographs of the EUT

Photo 1:



Photo 2:



2021-03-02 Page 3 of 5

Test report no.: 1-1068/20-01-07




Annex C: Internal Photographs of the EUT

Photo 1:



Photo 2:




2021-03-02 Page 4 of 5



Photo 3:



Photo 4:



2021-03-02 Page 5 of 5