



10. SETUP PHOTOS

OBW/TIMING MEASUREMENT






Note: Project number placard incorrect in above photo. Should be 13424287





RADIATED EMISSIONS



RADIATED EMISSIONS BELOW 30MHz






RADIATED EMISSIONS ABOVE 1000MHz





AC MAINS EMISSIONS



END OF TEST REPORT