



Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd.,Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12040901 Photo Page: 1 of 3

PHOTOS OF Testing

- Conducted test





Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd.,Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12040901

Photo Page: 2 of 3

Radiated test (below 1G , TX & Standby)





Spectrum Research & Testing Lab., Inc.

No.167, Ln. 780, Shan-Tong Rd.,Ling 8, Shan-Tong Li, Chung-Li City,
Taoyuan County 320, Taiwan (R.O.C.)

Reference No.: A12040901

Photo Page: 3 of 3

Radiated test (above 1G , TX & Standby)

