



6. Test Setup Photos

Radiated Emission



Conducted Emission





Electrostatic Discharge



Conducted radio frequency disturbance



<p>Radiated disturbance</p>	
<p>Fast transients (bursts)</p>	

7. External and Internal Photos of the EUT

Reference to the test report No.: CHTW24070080

-----End of Report-----