

ANNEX D

PHOTOGRAPHS (Number of photographs: 7)

Report No.: 25903RET

| Report No.: | D1 -f0 |
|------------------|--------------|
| 25903RET | Page: 1 of 8 |
| Date: 2007-06-25 | Annex D |
| | |



1. Equipment (front view)



| Report No.: 25903RET | Page: 2 of 8 |
|-------------------------|--------------|
| Date: 2007-06-25 | Annex D |



2. Equipment (back view)



| Report No.: 25903RET | Page: 3 of 8 |
|-------------------------|--------------|
| Date: 2007-06-25 | Annex D |

3. Equipment for conducted measurements





| Report No.: 25903RET | Page: 4 of 8 |
|-------------------------|--------------|
| Date: 2007-06-25 | Annex D |




4. General test set-up for radiated measurements.



| Report No.: 25903RET | Page: 5 of 8 |
|-------------------------|--------------|
| Date: 2007-06-25 | Annex D |




5. Test set-up for radiated measurements below 1 GHz.




| Report No.: 25903RET | Page: 6 of 8 |
|-------------------------|--------------|
| Date: 2007-06-25 | Annex D |




6. Test set-up for radiated measurements above 1 GHz.



| Report No.: 25903RET | Page: 7 of 8 |
|-------------------------|--------------|
| Date: 2007-06-25 | Annex D |







| Report No.: 25903RET | Page: 8 of 8 |
|-------------------------|--------------|
| Date: 2007-06-25 | Annex D |