# The Worst Case Configuration Photographs - TX without Headset

· · · ·	-
	Commentary .
	RADIATED
	Model No.: MR350
	Job No.: HK08111026 -1
	VA D.B6
· · · ·	

Radiated Emission

Front View

	RADIATED Model No.:
	Job No.: <u>HK08111026 -1</u>
1.7	

Rear View

## The Worst Case Configuration Photographs - TX with Extra Charger



Radiated Emission

Front View



Rear View

## The Worst Case Configuration Photographs – Weather Band Receiver



**Radiated Emission** 

Front View



Rear View


FCC ID: K7GMRCEJ

## The Worst Case Configuration Photographs – TX with PC Charging



Conducted Emission

Front View



Right Side View

## The Worst Case Configuration Photographs – TX with PC Charging

Conducted Emission



Left Side View

# The Worst Case Configuration Photographs – Weather Band RX with PC Charging



Conducted Emission

Front View



Right Side View

# The Worst Case Configuration Photographs – Weather Band RX with PC Charging

Conducted Emission



Left Side View