

INTERNAL PHOTOGRAPHS

This document contains 10 photographs

Photograph No.1
NV75MR PIR detector internal view




Photograph No.2
NV75MR PIR detector internal view




Photograph No.3
NV75MR PIR detector removed from case




Photograph No.4
NV75MR PIR detector removed from case




Photograph No.5
PCB front view with antenna




Photograph No.6
PCB second side view




Photograph No.7
Antenna close view



Photograph No.8
Antenna assembly



Photograph No.9
PCB front view close view



Photograph No.10
PCB second side close view

