

INTERNAL PHOTOGRAPHS




Figure 1. Top View with Cover Removed (Coil Antenna Exposed)




Figure 2. Side 1 (Antennas are the Rings with Yellow Tape)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

RSS 210
KE3-3001070
2721A-3001070
15-0197
August 11, 2015
RADIO SYSTEMS CORP
300-3078




Figure 3. Front

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

RSS 210
KE3-3001070
2721A-3001070
15-0197
August 11, 2015
RADIO SYSTEMS CORP
300-3078




Figure 4. Side 2

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

RSS 210
KE3-3001070
2721A-3001070
15-0197
August 11, 2015
RADIO SYSTEMS CORP
300-3078




Figure 5. Back of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

RSS 210
KE3-3001070
2721A-3001070
15-0197
August 11, 2015
RADIO SYSTEMS CORP
300-3078




Figure 6. Component Side of Main PCB