



Photo 1

Equipment under test

right: Transmitter CROS CTX

left: Receiver CROS CRX



Photo 2

Measurement of carrier and spurious emissions on CTX ($f < 30\text{MHz}$)



Photo 3

Measurement of spurious emissions on CRX ($f < 30\text{MHz}$)



Photo 4

Measurement of spurious emissions
($f > 30$ MHz)