

**APPENDIX I TEST PHOTOS**

Photo 1 Front of Conducted Disturbance Test



Photo 2 Rear of Conducted Disturbance Test



Photo 3 Front of Radiated Disturbance Test (Below 1GHz)




Photo 4 Rear of Radiated Disturbance Test (Below 1GHz)




Photo 5 Front of Radiated Disturbance Test (Above 1GHz)



Photo 6 Rear of Radiated Disturbance Test (Above 1GHz)

