

Report No.: 99023741


Tested By: Hong, Report No.: 99023741

Scan Settings (J Range) |-----| Receiver Settings |-----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10K	PK	20ms	AUTO	LN OFF	60dB

Transducer No.	Start	Stop	Name
3	9k	30M	21078

Final Measurement: X QP
 Meas Time: 1 s
 Subranges: 16
 Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A

Report No.: 99023741

Tested By: Hong, Report No.: 99023741

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A