




18. EUT SETUP PHOTOS



Radiated Emission Setup Photos (Worst Emission Position)



Conducted Emission Setup Photos (Worst Emission Position)

10 OF 14

COMPLIANCE ENGINEERING SERVICES, INC.

DOCUMENT NO:CCSTP4002B

NO.199, CHUNG SHENG ROAD, HSIN TIEN, TAIPEI, TAIWAN R.O.C.

TEL: (02) 2217-0894 / FAX: 2217-1254

This report shall not be reproduced except in full, without the written approval of CES.