Report No: 9122106-RP2

FCC ID: M82-PIT-1501

Date of Issue: January 29, 2010

APPENDIX I PHOTOGRAPHS OF TEST SETUP

Radiated Emission Set up Photos Below 30MHz









COMPliance Certification Services Inc.

Report No: 9122106-RP2 FCC ID: M82-PIT-1501 Date of Issue: January 29, 2010

30 ~ 1000MHz





Report No: 9122106-RP2

FCC ID: M82-PIT-1501

Date of Issue: January 29, 2010

Powerline Conducted Emissions Setup Photos



