

Correspondence by Project

Project Number:

-500866085

Correspondence Number	Memo
MG33005-1	<p>Regarding your questions. 1) Please provide correct schematics. The schematics provided do not match the internal photos of the device. Specifically, the values of C28, R11 and R28, among other components, do not match what is shown in the internal photos. Please see the uploaded revised schematics. 2) The report uses a duty cycle correction factor, however there is no duty cycle information. Please provide information regarding the duty cycle. Please see the uploaded duty cycle plots.</p>