


Part 22H & Part 24E Test Setup Photographs

Conducted Emissions Test Configuration:



Rear View



Report Number: 1007FR11 Page 1 of 3



Radiated Emissions Test Configuration:



Below 1GHz _ Rear View



Report Number: 1007FR11 Page 2 of 3



Above 1GHz _ Front View

ATEST

1007FR11

Above 1GHz _ Rear View



Report Number: 1007FR11 Page 3 of 3