


6 Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emission Measurement



BH201

Prüfbericht - Nr.:
Test Report No.:

16010811 001

Seite 32 von 34
Page 32 of 34

Photograph 2: Set-up for Radiation Measurement below 1GHz

=



Prüfbericht - Nr.:
Test Report No.:

16010811 001

Seite 33 von 34
Page 33 of 34

Photograph 3: Set-up for Radiation Measurement above 1GHz

