

Prüfbericht - Nr.: 16015361 001
Test Report No.:

Seite 18 von 21
Page 18 of 21

6 Photographs of the Test Set-Up



Photograph 1: Set up for Conducted Emission on AC Mains



Prüfbericht - Nr.: 16015361 001
Test Report No.:

Seite 19 von 21
Page 19 of 21

Photograph 2: Set-up for Radiation Measurement below 1GHz



Prüfbericht - Nr.: 16015361 001
Test Report No.:

Seite 20 von 21
Page 20 of 21

Photograph 3: Set-up for Radiation Measurement above 1GHz

