



Test setup photographs for test report 250332


Photograph 1. Spurious radiated emissions test setup (setup4)



Photograph 2. AC power line conducted emissions test setup (setup4)




Photograph 3. setup1, without power supply



Photograph 4. setup2, without power supply



Photograph 5. setup3, without power supply



Photograph 6. setup4, without power supply