


Test report No.	FCC_IC_RF_SL15081301-SLX-017_DTS_2.4G
Page	7 of 20


<u>6.4</u> <u>EUT Test Setup Photos</u>







Radiated Emissions (<1GHz) - Front View









Radiated Emissions (>1GHz) - Rear View