

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

Worst Case Position
(Module/Antenna Horizontal: X-axis/Y-axis , Vertical: X-axis/Z-axis)


<Antenna>
X-axis




Y-axis




Z-axis




<Module>
X-axis



Y-axis



Z-axis



End of Report